

Table of Contents

- 1 Utilization of Polymers to Improve Soft Clayey Soils Using the Deep Mixing Method**
Seracettin Arasan, Majid Bagherinia, R. Kagan Akbulut, and Ahmet Sahin Zaimoglu
- 13 Three-Dimensional Stability Assessment of a Complex Landslide in the Rječina Vally, Croatia**
Chunxiang Wang
- 23 Assessment of the Mechanism of a Slope Failure in a Hydroelectric Power Plant Site and Considerations on Some Remedial Measures**
Ergün Tuncay and Resat Ulusay
- 43 Assessing the Geological Sources of Manganese in the Roanoke River Watershed, Virginia**
Zachary A. Kiracofe, William S. Henika, and Madeline E. Schreiber

